

Case Study

Refueling Bunded Area Crown Bus Lines

The refueling area at Crown Bus lines was bunded by a Raised Concrete edge
As the rest of the area was concrete it was very hard to identify as a result there was many injuries with ankles and backs.

AWIS Preform was consulted and provided a non skid preform to cover the raised bunded area. AWIS Preform suggested a yellow black cross hatched as identification.



The refueling bunded area. It is very hard to identify the raised bunds.



The AWIS Preform highlights the bunded area and as it is anti slip it is safe to walk over and the retroreflectivity allows it to be identified when the headlights of the buses shine on it.



AWIS PREFORM

A: PO Box 98 Bayswater VIC 3153

P: 03 9720 2803

F: 03 9729 0121

M: David 0417 052 443

M: Terry 0412 854 241